
MARION COUNTY SURVEYOR'S OFFICE

DEBRA S. JENKINS MARION COUNTY SURVEYOR SECTION CORNER RECORD SEC. 34 TWN. 15_{N} RNG. 5_{E}

BRYAN F. CATLIN, PLS TECHNICAL SUPERVISOR



Original post set 1820 by John Hendricks with witnesses: 10" beech S 1 E 39 links, 12" dogwood N 58 W 44 links per Marion County Atlas pg. 14. Survey by D.B. Hosbrook 6-17-1856 indicates no stone but witness: 16" beech S 75 1/2 W 43 links per Franklin Township Legal Survey Book pg. 15. Monroe 6-13-1952 called a stone. MCSO 1960 called a stone. Fleener 10-23-70 called a rebar set over stone 18" down. McLand 4-26-72 called the same. Fortner 2-20-75 called a cut 'x' in RR spike over rebar over stone 19" down. Hancock County 5-20-77 called a brass plug and plate set by them. Hancock County 10-4-79 called a brass plug and plate. Wilcoxen 3-15-88 called the same. Excavated by Kiste 12-17-99 and a copperweld in octagonal plate was found 3" down. A 1 1/2" steel pin was found 18" down. A stone was found 24" down. Harrison was set. Retied 6-28-2005 by Wilcoxen. Retied 6-9-09 by Greene.

REF.	DISTANCE	DESCRIPTION
1.	18.84'	Mag nail NW PwP #1-681 15" up
2.	23.17'	Face of steel fence post
3.	75.69'	PK nail S PwP #29-681 P
4.	67.80'	Cut 'x' S end of concrete headwall